

BRAVO SPOTTER

BOX EXTRACTORS

Upholstery Cleaner



Optional Wand



Roll Away Design



**AVAILABLE
WITH
HEAT!**

The new Bravo spotter delivers incredible efficiency and power in a deceptively small package. No set up time—simply unload and begin cleaning immediately. Compact size and maneuverability make it ideal for spotting and quick cleaning of small carpeted areas, upholstery and auto interiors. Operators will appreciate the specially designed molded-in holders that carry spray bottles, leaving the hands free.

Over time it's a winner too, thanks to the upright-mounted vacuum motor and oversized recovery tank that combine to ensure longer motor life.



BRAVO SPOTTER

Features & Benefits

- Optional in-tank heater delivers 150-degree heat. (300MH-HT)
- Unique molded-in holders carry spray bottles for greater ease
- Large six-inch wheels and transport handle plus cord wrap assembly make it a snap to wheel about
- Quickly opens up for easy servicing and repair
- Large porthole on recovery tank allows easy access for odor-free maintenance

	300MH	300MH-HT
Solution Tank	3 gallon	3 gallon
Recovery Tank	3.5 gallon	3.5 gallon
Solution Pressure	55 psi	55 psi
Vacuum Motor	2-stage, bypass	2-stage, bypass
Water Lift	106 inches	106 inches
Handle	Adjustable, 22-37"	Adjustable, 22-37"
Wheels	6 inches	6 inches
Power Cord	25 ft.	25 ft.
Heater	N/A	1500 watts, stainless steel
Weight	19 lbs.	19 lbs.
Shipping Weight	27 lbs.	27 lbs.
Dimensions	20.5" H x 15" L x 13" W	20.5" H x 15" L x 13" W
Shipping Dimensions	23" H x 18" L x 15.5" W	23" H x 18" L x 15.5" W
Electrical Draw	12 amps	15 amps

OPTIONAL ACCESSORIES

839ACK	8' hose and stainless steel upholstery/stair tool assembly (1039-9502FB tool)
1204ACH	Powermate – 12" wide power brush
330-1103FB	10" single-jet wand
342AC	8-ft. hose assembly with quick disconnects
323ACH	Prespray wand
1039-9502FB	Stainless steel upholstery/stair tool
1037-9502FB	Stainless steel upholstery/stair tool with plastic see-through head



839ACK



1204ACH



330-1103FB




342AC



323ACH



1037-9502FB



1039-9502FB